

HIGH CAPACITY AUTOMATIC FEEDERS MODELS HC-3315, HC-3330, HC-3340

REPLACEMENT PARTS



Item	Qty.	Part No.	Description
Order No.: R171215, R171230, R171240			
Model No.: HC-3315, HC-3330, HC-3340			
Description: HIGH CAPACITY AUTOMATIC FEEDER			
1	1	R172214	Lock ring
2	1	R172385D	Lid assembly complete
3	1	R172224X	Vent valve
4	1	R172221	O-ring vent valve
5	1	R172240	O-ring lid to housing
6	1	R172375	Lock screw
7	1	R172374	Lock spring
8	1	R175251	Screen
8A	1	R171919	Check Valve Seat
9	1	R172435	Check ball
11	2	R270484	1 in. Close nipple
12	1	R270531	1 in. Threaded union
13	1	R172439	Control valve
14	1	R172036Z	Silicone lubricant, 3/4 oz.
15	Opt.	R172288	1-1/2 in.-2 in. Check valve
16	1	R175009	Hose Bib w/t Handle 1/2 in.
17	1	R172134	1/2 in. threaded plug
NOT SHOWN			
		R172082	Flow rate indicator

CALIFORNIA PROPOSITION 65 WARNING

⚠ **WARNING:** Cancer and Reproductive Harm.
 ⚠ **AVERTISSEMENT:** Peut Causer le Cancer et des Dommages au Système Reproducteur.
 ⚠ **ADVERTENCIA:** Cáncer y Daño Reproductivo.
www.p65warnings.ca.gov