


INTELLIBRITE® 5G WHITE LED LIGHTS

2ND GENERATION AFTER 2010 REPLACEMENT PARTS



CALIFORNIA PROPOSITION 65 WARNING

⚠ **WARNING:** Cancer and Reproductive Harm.
 ⚠ **AVERTISSEMENT:** Peut Causer le Cancer et des Dommages au Système Reproducteur.
 ⚠ **ADVERTENCIA:** Cáncer y Daño Reproductivo.

www.p65warnings.ca.gov
PK 201714

Item	Part No.	Description
INTELLIBRITE WHITE LED POOL LIGHTS		
	620276	Replacement fuse for 12V only lights (For lights built after Oct. 2015)
1	79104800Z	Pilot screw with captive gum washer, brass
1	619355Z	Pilot screw with captive gum washer, SS
1	600095	Face ring, clamp, and gasket kit
2	79110600	Face ring assembly, SS
3	79111000	Uni-tension wire clamp assembly
4	619864Z	Lens and gasket assembly, tempered
5	620400Z	Gasket, 8-3/8 in. diameter, silicone
6	620141	Nut, retaining
	619875Z	IntelliBrite 5g white LED 300w replacement engine
	619916Z	IntelliBrite 5g white LED 400w replacement engine
	619917Z	IntelliBrite 5g white LED 500w engine
INTELLIBRITE WHITE LED SPA LIGHTS		
1	79104800Z	Pilot Screw, with captive gum washer, brass
1	619355Z	Pilot screw with captive gum washer, SS
2	79111600	Face ring assembly, S/S
3	79210400	Uni-tension wire clamp assembly w/ welded nut
	640046	Lens Kit (includes items 4 and 5)
5	79108600	Gasket, white, silicone

Note: IntelliBrite Spa light has no user serviceable parts inside.